


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-294	Smoke	9/10/2009	ADS/TM	S09MM1022MH	Dry	Yes	49.98



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-294	Smoke	9/10/2009	ADS/TM	S09MM1022MH	Dry	Yes	49.98

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09MM1022G1	S09MM1022MH	S09MM1039MH	49.9838	8

Observations & Photos

Obs_ID S1028-294-OB01

Address 4900 Denmore Ave

Status Public

Source Catch Basin

Location Curb

Nearest MH S09MM1022MH

Comments Smoke from catch basin along curb in front of 4900 Denmore Ave.



Picture \S1028-294-OB01-P01.jpg

Comments Front of house, 4900 Denmore Ave.

